

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-4096	DATE	October 23, 2025
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	The Heating, Ventilation and Air Conditioning (HVAC) blower motors may have been built with a connector with recessed pin moved from its original position, resulting in an electrical connection susceptible to failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-WL20	「Grand Cherokee」	2023	57
3LA-WL20A	「Grand Cherokee」	2023	81
7BA-WL20	「Grand Cherokee」	2023	274
7BA-WL36L	「Grand Cherokee L」	2023	6
7BA-WL36LA	「Grand Cherokee L」	2023	48
		TOTAL	466