

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4214	DATE	23, July, 2026
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the driver assistance system control unit, the transmission of camera image signals may be interrupted due to an improper control program. As a result, the image of the top view system will not be displayed, and image of the left (right) front lower of the vehicle cannot be confirmed, and there is a risk that it will not compliant with the safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-ZLDHU	URUS	2019-2020	712
7BA- ZLDHU		2020-2024	739
7BA- ZLDWN		2023-2024	695