VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~／Import Vehicles

CAMPAIGN No.	GAI 4240	DATE	30/Sep/2026
MANUFACTURE	SCANIA CV AB （Japanese Importer: SCANIA JAPANA Co. Ltd. ）		
DESCRIPTION OF DEFECT	The control software of the Center Information Display (CID) control unit may not function properly during a voltage drop due to insufficient design consideration. Consequently, the images from the front-left proximity monitoring camera and the rear-view camera may not be displayed on the CID, resulting in non-compliance with the applicable safety standards		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2024-2026	1,333
		TOTAL	1,333