

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

|                       |   |      |               |
|-----------------------|---|------|---------------|
| CAMPAIGN No.          | 5178  | DATE | July 15, 2022 |
| MANUFACTURER          | SUMITOMO NACCO FORKLIFT CO., LTD.<br>(Japan)  |      |               |
| DESCRIPTION OF DEFECT | The optional grip with an alarm device is mounted on the right rear side of the overhead guard, and as that alarm sound is different from the alarm sound of the vehicle inspection specification, pedestrians and other traffic may misrecognize it. |      |               |

| TYPE    | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|-----------------|---------------------|-------------------|
| XDN-D4K | FD40PAXII       | 2016                | 1                 |
|         |                 | TOTAL               | 1                 |