VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5208	DATE	Sep. 16. 2022
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain voltage converters of light-duty trucks, because assembly instructions of a wiring take-out part is inappropriate, water may enter a voltage converter from the wiring take-out part and an abnormality may be detected. Therefore, the warning display illuminates and the fail- safe mode is set to restrict the vehicle speed. If the vehicle is used continuously, charging of the auxiliary battery may become insufficient, causing the vehicle to stop running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-XED100V	[HINO DUTRO Z EV]	2022	9
XED100	[-]	2021	3
		TOTAL	12