## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5271	DATE	Feb.2.2023		
MANUFACTURER	ΤΟΥΟΤΑ				
DESCRIPTION OF DEFECT	In a Panoramic View Monitor system, due to an improper programming, there is a possibility that the camera image may stop, and the surrounding area of the vehicle cannot be provided correctly. This could reduce the driver's left side view.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-MXPH10	[YARIS]	2019-2021	11,723	Equipped with Panoramic
6AA-MXPH15			2,107	View Monitor with Advanced
6AA-MXPJ10	[YARIS CROSS]	2020-2021	7,463	Park
6AA-MXPJ15			3,098	
		TOTAL		24,391