

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5332	DATE	2023/6/5
MANUFACTURER	TANK TEC CO.,Ltd		
DESCRIPTION OF DEFECT	In a trailer with a lift axle function, the clamping plate securing the air spring for lifting the lift device was broken, and parts of the lift device were found to have fallen off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TTW180A	-	2022	1
TTW200A	-	2021	2
TTX170A	-	2022	1
types in total	models in total	Overall range of production period 2021-2022	4