

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5494	DATE	June 6, 2024
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	The air deflector installed under the floor in front of the rear wheel does not conform to the Technical Standards for Exterior Fittings (UN Regulation No. 26) because the shape verification at the time of development was insufficient.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA650S	TANTO	2022-2024	35,853
5BA-LA660S			8,974
		TOTAL	44,827