

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5529	DATE	September 5, 2024
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On certain center display (10.25 inch), due to inappropriate program to correct image, when display switching from TV screen to other screen such as Navigation system, it may cause to display image distortion. As the result, the monitor may display not camera image but stripe pattern.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-KF2P	Mazda「MAZDA CX-5」	2023-2024	3,722
6BA-KF5P			504
6BA-KFEP			1,542
3DA-KG2P	Mazda「CX-8」	2023-2024	3,002
6BA-KG5P			1,202
		Total	9,972

THE CASE OF IMPOSSIBLE TO IDENTIFY VEHICLES REPLACED WITH REPAIR PART

NAME OF THE SUBJECT PART	PART No.	SHIPPING PERIOD OF THE SUBJECT PART	NUMBER OF THE SUBJECT PART	REMARK
CENTER DISPLAY	K19G-611J0C	NOVEMBER, 2023 -DECEMBER, 2023	5 units	「MAZDA CX-5」、 「CX-5」、「CX-8」
		TOTAL	5 units	