

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5629	DATE	Mar.26.2025
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the frame of the Mobile Toilet (excrement full trailer), due to insufficient consideration of durability, there is a possibility that cracks could develop on the frame by stress generated during driving. If the vehicle is continuously operated in this condition, the cracks could expand and, in the worst case, the frame may break, resulting in the vehicle becoming inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
MT018	—	2024	8	experimental car
		TOTAL	8	