## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Qomestic Import Vehicles

CAMPAIGN NO.	5641	DATE	April 10 ,2025
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		The Vehicle Identification Number (VIN) cannot be displayed on general scan tools, due to the improper instruction for programming the parameter into the engine control unit. Therefore, this fails to comply with the safety standards.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2PG-FVR26U4	[FORWARD]	2024	20
2DG-FVZ26U4		2024	126
2KG-BVR26U4□ 2PG-BVR26U4	[CONDOR]	2024	4
2DG-BVZ26U4		2024	23
		TOTAL	173