

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	5673	DATE	June 26 ,2025
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Some interior rearview mirrors (convex mirrors) have a smaller mirror surface width due to the inappropriate dimensional control in the manufacturing process. Therefore, the mirror surface width of interior rearview mirrors may not comply with the structural requirements for one-man buses, buses without a conductor.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-LV234L3□ QPG-LV234L3□ QQG-LV234L3□ QSG-LV234L3	[ERGA]	2012-2017	10
QDG-LV234N3□ QKG-LV234N3□ QPG-LV234N3□ QQG-LV234N3		2012-2017	218
QDG-LV234Q3□ QKG-LV234Q3□ QPG-LV234Q3		2012-2017	27
QDG-LV290N1□ QKG-LV290N1□ QPG-LV290N1		2015-2017	254
2DG-LV290N2□ 2KG-LV290N2□ 2PG-LV290N2		2017-2019	128
2DG-LV290N3□ 2KG-LV290N3□ 2PG-LV290N3□ 2RG-LV290N3□ 2TG-LV290N3		2019-2023	158
2KG-LV290N4□ 2RG-LV290N4		2023-2024	106
QDG-LV290Q1□ QKG-LV290Q1□ QPG-LV290Q1□ QRG-LV290Q1		2015-2017	151

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-LV290Q2□ 2PG-LV290Q2□ 2TG-LV290Q2	[ERGA]	2017-2019	154
2KG-LV290Q3□ 2PG-LV290Q3□ 2RG-LV290Q3□ 2TG-LV290Q3		2019-2023	160
2KG-LV290Q4□ 2RG-LV290Q4□ 2TG-LV290Q4		2023-2024	92
SDG-LR290J1□ SKG-LR290J1	[ERGA MIO]	2012-2016	226
SKG-LR290J2		2016-2017	127
2KG-LR290J3		2017-2019	223
2KG-LR290J4		2019-2023	308
2KG-LR290J5		2023-2024	191
LX525Z1	「—」	2020-2024	11
2SG-HL2ANBD	[ISUZU ERGA]	2022-2024	8
2SG-HL2ASBD		2018-2024	14
		TOTAL	2,566

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF□ VEHICLE
Mirror	4-63511147-0	2012-2024	44
		TOTAL	44