

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5759	DATE	February 12, 2026
MANUFACTURE	SUMITOMO NACCO FORKLIFT CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	Due to insufficient design review, the mounting position of the keypad used for password entry on forklifts with special order specifications does not comply with Safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB1H	FB15PSE	2009	1
SB2H	FB15PJSE	2010	3
ZAF-SB1J	FB15PSE	2013	1
ZAF-SB1K	FB15PSXII	2015	2
ZAF-SB1L	FB15PSXIII FB15PJSXIII	2017 - 2023	4
		TOTAL	11