

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	5805	DATE	April 20 ,2026
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		On certain medium-duty trucks equipped with a double cab (fire trucks), the left-side radar for the blind spot information system has been installed incorrectly due to unclear installation instructions. As a result, if the vehicle continues to be used in this condition, the radar's angle learning function will detect the abnormality, displaying "Left-side radar temporarily stopped" on the meter display, illuminating the "Blind spot monitor OFF indicator" and disabling the blind spot information system.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FSR90S4	"FORWARD"	2024 – 2025	25
2PG-FSS90J4		2024 – 2025	12
2RG-FRR90S4		2024	1
		TOTAL	38