

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5840	DATE	2026/6/30
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	For a van-type truck, the rear combination lamps are installed incorrectly. Because of improper mounting instructions, the position of the tail lamps or rear reflectors does not comply with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-CG5CA	QUON	2021~2022	2
2KG-XZU712M	HINO DUTRO	2024	1
TOTAL			3