

Drainpipes

Soon after the keep was completed, the castle's occupants noticed that rainwater often collected in its many window frames—a serious problem for a wooden structure. If the wooden frames became saturated with water, they would expand and damage the walls from the inside. These metal pipes were added to drain the water and prevent any damage.